

APPENDIX 10

WAGONS – CORRECTIVE AND PREVENTIVE MAINTENANCE

1.15.1 Axles must not:

- show any cracks or any defects repaired by welding;
- be warped;
- have any part worn by friction showing sharp edges (sharp-edged notches);
- show any kind of wear by friction exceeding 1 mm in depth.

Brake rods or other parts must not rub on the axles.

1.15.2* The instructions of Annex 3 must be applied.